


SMOKE CHAMBERS

What You Should Know



Many masonry fireplaces are in need of help. Time, heat, moisture and acid attack have taken their toll on the complete system, not to mention poor design during construction. Chimneys can be relined and fireboxes can easily be repaired, but until the development of CHAMBER-TECH 2000 the smoke chamber between the firebox and chimney had often been neglected.

The smoke chamber is crucial to the proper performance and safe burning of a fireplace. Often masons would leave this area corbeled and rough which would cause turbulent draft. Cleaning and maintenance would also be very difficult. Combustible building materials are often too close and risk overheating.

CHAMBER-TECH 2000 is the answer to those rough, deteriorated, uninsulated and improperly formed smoke chambers. CHAMBER-TECH 2000 will insulate, reducing conduction to combustible materials, add needed structural strength and at the same time shape the smoke chamber for efficient flow of smoke and gasses. Cleaning and maintenance will become much easier in the future.

CHAMBER-TECH 2000 is the cost effective solution to fireplace smoke chamber problems.

CHIMNEY SWEEP MASTER

847-516-4139 426 Lloyd St., Cary, IL 60013



The Problems

- Turbulence/Very Inefficient
- Uninsulated/Much Heat Loss
- Heat Transfers To Combustibles
- Area Weakened From Use And Time
- Needs Structural Strength
- Builds Up Creosote Faster
- Hard To Clean
- Inadequate Clearance To Combustibles



The Solution


- Fluent Efficient Flow Of Smoke/Combustion By-Products
- Smooth Surface/Less Friction/No Turbulence
- Insulated/Increased Efficiency/Less Heat Transfer
- Structural Strength Added
- Less Creosote Build-Up
- Easier To Clean And Maintain
- Cost Effective Compared To Alternatives

Bring Most Existing Smoke Chambers "Up To Code"

SPECIFICATIONS



- Minimum 1 1/2" Thickness Of **Chamber-Tech 2000** Required
- Masonry Can Be As Thin As 4" Nominal Thickness
- Combustibles Can Be Touching The Masonry
- Brings Most Smoke Chambers "Up To Code"
- Reduce **Your** Risk Of Fire And Smoke Leaks
- Can Be Used On Any Masonry Smoke Chamber Configuration
- Can Be Built Up To Any Thickness
- Adheres To Any Masonry Surface



YOUR FIREPLACE PROFESSIONAL

CHIMNEY SWEEP MASTER

426 Lloyd St., Cary, IL 60013

847-516-4139

goodchimney.com


A PRODUCT OF



Ahrens Chimney Technique Inc.

2000 Industrial Ave • Sioux Falls, South Dakota 57104

©Ahrens Chimney Technique Inc. 2018



FOR FIREPLACE SMOKE CHAMBER RESTORATION



**ZERO CLEARANCE
TO COMBUSTIBLES**

A Product Of

